

SAMPLE / DEMO REPORT

Quality Inspection Report

Pre-Shipment Inspection (PSI) — AQL 2.5 / Level II

This document uses illustrative sample data for demonstration purposes only. It shows the structure and level of detail of an actual FULITES inspection report.

REPORT NO.

FUL-2026-00842

INSPECTION DATE

09 July 2026

RESULT

PASS

Report Overview

Client (Buyer)	Northgate Home Imports LLC (USA) — sample data
Product	Solid Acacia Wood Dining Chair, Model NH-CH114
Supplier / Factory	Sample Furniture Co., Ltd. — Binh Duong, Vietnam
Order Quantity	1,240 pcs
Inspected Quantity	80 pcs (AQL 2.5 / General Inspection Level II)
Inspection Type	Pre-Shipment Inspection (PSI)
Inspector	N. Van Thanh — FULITES Field Inspector #FT-014

1. General Information

Report No.	FUL-2026-00842
Inspection Date	09 July 2026
Inspection Type	Pre-Shipment Inspection (PSI)
Client (Buyer)	Northgate Home Imports LLC — 8 Harbor Rd, Portland, OR, USA (sample data)
Supplier / Factory	Sample Furniture Co., Ltd.
Factory Address	Lot C4, An Tay Industrial Park, Binh Duong Province, Vietnam
Product	Solid Acacia Wood Dining Chair — Model NH-CH114
Purchase Order No.	PO-88214
Order Quantity	1,240 pcs
Inspected Quantity	80 pcs
Sampling Standard	ISO 2859-1, General Inspection Level II
AQL Applied	Critical: 0 / Major: 2.5 / Minor: 4.0

Note: All figures on this page are illustrative sample data used to demonstrate report format and are not a real inspection record.

2. Overall Conclusion

● **RESULT: PASS**

Based on the sampling result, the shipment meets the buyer's AQL 2.5/4.0 acceptance criteria. One major defect was found within the accept range for the sample size used (see Section 5).

3. Product Photos

Illustrative placeholders below — a real FULITES report includes actual on-site photographs.

PRODUCT PHOTO Front view — assembled unit	PRODUCT PHOTO Packaging / carton	PRODUCT PHOTO Label / barcode close-up
---	--	--

4. AQL Sampling Result

AQL Sampling Result		
Classification	Accept (Ac)	Reject (Re)
Critical	0	1
Major (AQL 2.5)	5	6
Minor (AQL 4.0)	7	8

5. Workmanship Defects Found

#	Defect Description	Location	Classification	Qty
1	Minor surface scratch on chair leg finish	Rear left leg	Minor	3
2	Slight color variation between batch units	Backrest slats	Minor	2
3	Loose screw on seat frame joint	Underside frame	Major	1
4	Packaging carton corner crush (< 5 cm)	Export carton	Minor	2

Result: 1 Major + 5 Minor found — within accepted range for sample size n=80 (Ac 6 Major / Ac 8 Minor).

6. Measurement Check

Measurement Point	Spec (cm)	Tolerance	Sample Avg.	Result
Seat height	46.0	± 0.5	46.2	OK
Overall width	52.0	± 0.8	51.7	OK
Overall depth	55.0	± 0.8	55.4	OK
Backrest height	88.0	± 1.0	88.6	OK

Result: All measured dimensions within specified tolerance.

7. Packaging & Labeling Review

Export Carton	1 pc per carton, 5-layer corrugated board — condition: acceptable, 2 cartons with minor corner crush
Inner Packing	EPE foam corner protectors + poly bag — sufficient for transit protection
Carton Marking	PO number, item code, quantity, country of origin — all present and legible
Shipping Marks	Consistent with buyer's packing instructions v.3
Barcode Scan Test	20/20 cartons scanned successfully

8. Defect Photos

Illustrative placeholders below — a real FULITES report includes close-up photos of each defect listed in Section 5.

DEFECT PHOTO Ref. #1 — surface scratch	DEFECT PHOTO Ref. #3 — loose screw	DEFECT PHOTO Ref. #4 — carton crush
--	--	---

This report reflects the condition of the inspected goods at the date and time of inspection only, based on a statistical sample per ISO 2859-1. FULITES acts exclusively on behalf of the buyer and is fully independent of the factory named in this report.

Inspected by N. Van Thanh FULITES Field Inspector #FT-014	Reviewed by T. Thi Mai FULITES QC Supervisor	Report issued 10 July 2026 FULITES Vietnam
--	---	---